


3.1: Front (east) facade with names of architectural features.



3.2: Three dimensional drawing of principal steeple framing as viewed from front with primary structural issues noted. Age of various past replacement timbers is indicated by colors.